


4

Print picture

Click the button



Waiting for Printing to Finish



• The Bottle Off Hole checkbox must be checked, then the parameter is 3/1. then save the parameter.

- click ,stop printing.
- click pause Print Action.
- Press the keyboard Delete key to delete the data in the selected print list.